



FALKLAND ISLANDS GOVERNMENT

NOTICE TO MARINERS

N^o 01/2026

Stanley Harbour

Small Yacht Moorings

Central Mooring Buoy Out of Service

1. The central mooring in position 51°41.400'S 057°51.730'W is out of service until further notice and is not to be used. It has been marked by a pellet buoy but this is not suitable for mooring purposes.
2. The remaining buoys in positions 51°41.390'S 057°51.820'W and 51°41.410'S 057°51.650'W remain in service and are still available for use.



Stuart Barlow MNI
Harbour Master,
Falkland Islands Government.
Issued on 15/01/2026